

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403780947

Date Received:

05/07/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Michael Cugnetti

Phone

720-845-6901

Email

mcugnettti@verdadresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696306246

Inspection Date: 04/18/2024

FIR Submit Date: 04/18/2024

FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 467102

Location Name: Bringleson Fed Number: 2021-2029 County: _____

Qtrqtr: SESE Sec: 20 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.730847 Longitude: -103.880722

FACILITY - API Number: 05-123-00 Facility ID: 467102

Facility Name: Bringleson Fed Number: 2021-2029

Qtrqtr: SESE Sec: 20 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.730847 Longitude: -103.880722

CORRECTIVE ACTIONS:

1 CA# 194382

Corrective Action: Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

Date: 05/03/2024

Response: CA COMPLETED

Date of Completion: 05/03/2024

Operator Comment: OOSLAT applied to the risers and flowlines. OOSLAT will stay in place at all times during the process of abandoning the flowline until the operator removes the riser. See attached photo documentation of corrective action.

ECMC Decision: _____

--

Date: 5/7/2024 9:01:30 AM

Total Attach: 1 Files