



99999999

OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- <u>123</u> - <u>05291</u>		LEASE NAME: <u>Kindson Res #1</u>	
LOCATION: <u>534-7N-67W</u>		OPERATOR: <u>Chevron USA</u>	
DATE: <u>2/12/98</u>		INSPECTOR: <u>Paul KA</u>	
Insp. Type: <u>HR</u>	Insp. Status: <u>PA</u>	PA: <u>Y</u> <u>N</u>	Pass/Fail: <u>P</u> <u>F</u> Viol.: <u>Y</u> <u>N</u> NOV: <u>Y</u> <u>N</u>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		

RECEIVED
MAR 5 98
COGCC


00217096

CORRECTIVE ACTION REQUIRED: <u>No surface disturbance found</u>	
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

9-30-1969

COLORADO
WELD COUNTY
NEW WINDSOR (D)



Twp: 7n-67w
Section 34
sw ne ne

OPR: The California Co.

WELL #: 1 New Windsor Reservoir, Canal et al

ELEV: 4950 KB.

*TOPS: Log ~~8228~~
Hygiene 4272
Timpas 7154
Carlile 7175
Greenhorn 7382
Graneros 7463
D Sd 7659
J Sd 7885
Entrada 8265
Jelm 8298
Lykins 8351
Upper Satanka 8865
Lyons 8986
Lower Satanka 9029

DSTS. & CORES:
DST 4264-4325, 2 hrs,
rec 295 HO&GCM, 15%
oil, FP 83-143#, SIP
(45 min) 1680#, HP 2112#.

SPUD: 5-14-57 COMPL: 6-26-57
TD: 9065 PB: 4307
CSG: 10-3/4" @ 428 w/250
7 1/2" @ 4398 w/175
PERF: 4272-91 w/8 per ft.

PROD. ZONE:

INIT. PROD: IPP 55 BOPD

C5-75527

oil

*For Electric Logs on Rocky Mountain Wells—Ask Us!

made folder 9-30-69

Blanket Bond for Smith. 9/24/69 —

File missing

COLORADO OIL & GAS CONSERVATION COMMISSION

1150 Lincoln Street, Suite 801

Denver, CO 80203

RECEIVED