

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403784072

Date Received:

05/08/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

3 of 6 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Newville, Toni

toni\_newville@oxy.com

Sanchez, Chris

chris.sanchez@state.co.us

ECMC

dnr\_cogccenforcement@state.co.us

ERIN JOSEPH

970-515-1169

ECMCInspections@Oxy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 713600952

Inspection Date: 04/16/2024

FIR Submit Date: 04/18/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: OXY USA INC

Company Number: 66561

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-3779

#### LOCATION - Location ID: 324493

Location Name: GARCIA-627S70W Number: 35NESE County: HUERFANO

Qtrqtr: NESE Sec: 35 Twp: 27S Range: 70W Meridian: 6

Latitude: 37.655840 Longitude: -105.180780

#### FACILITY - API Number: 05-055-00 Facility ID: 211777

Facility Name: GARCIA (EPA) Number: 1-WD

Qtrqtr: NESE Sec: 35 Twp: 27S Range: 70W Meridian: 6

Latitude: 37.655840 Longitude: -105.180780

### CORRECTIVE ACTIONS:

3 CA# 194377

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/30/2024

SEE ATTACHED PHOTOS OF REPAIRED FENCING

Operator Comment:	
ECMC Decision:	
ECMC Representative:	

**5** CA# 194379

Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)	Date:	
Response:	CA COMPLETED	Date of Completion:	04/30/2024
Operator Comment:	WATTLES HAVE BEEN REPLACED SEE ATTACHED PHOTOS		
ECMC Decision:			
ECMC Representative:			

**6** CA# 194480

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o Comply with Rule 902.b. for pollution prevention.	Date:	
Response:	CA COMPLETED	Date of Completion:	04/30/2024
Operator Comment:	SEE REPAIRED BERMS IN PHOTOS ATTACHED		
ECMC Decision:			
ECMC Representative:			

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN JOSEPH Signed: \_\_\_\_\_

Title: SR REGULATORY ADVISOR Date: 5/8/2024 2:24:05 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403784083	REWORKED BERMS
403784085	WATTLES REPLACED
403784088	PERIMETER FENCE REPAIRED

Total Attach: 3 Files