

FORM
6A
Rev
08/22

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403775931

Date Received:
05/09/2024

Rule 434.d. Out of Service Designation and Plugging List. An Operator will designate a Well as Out of Service on a Form 6A, Out of Service Designation, and the Out of Service Well is then placed on the Operator's Plugging List.

OUT OF SERVICE DESIGNATION

OPERATOR & CONTACT INFORMATION

ECMC Operator Number: 41550

Name of Operator: TYLER ROCKIES EXPLORATION LTD

Address: P O BOX 119

City: TYLER State: TX Zip: 75710-0119

Contact Name and Telephone:

Name: Mark Strawn

Phone: (903) 595-4886

Email: texcomo@sbcglobal.net

WELL PLUGGING DATA

The number of Wells the Operator has plugged in the previous 12 months:

EVIDENCE OF FINANCIAL CAPABILITY

Provide evidence that the Operator is financially capable of meeting the timelines required by Rule 434.d.(4) for its Plugging List. (If this space is inadequate, provide as an attachment.)

Pursuant to Colorado Oil and Gas Conservation Commission ("Commission") Rule 702.c.(6).D., Tyler Rockies Exploration LTD (Operator No. 41550) hereby submits this Certification of Financial Capability as evidence that Tyler Rockies Exploration LTD is financially capable of meeting all of the obligations imposed by the Act and Commission's Rules.

OUT OF SERVICE DESIGNATION

Summary of Wells to be Designated as Out of Service and placed on the Operator's Plugging List

Within 2000' of a School Facility 0

Within 2000' of a Child Care Center 0

Within 2000' of a High Occupancy Building Unit 0

TOTAL NUMBER OF WELLS 5

Valid 5 Invalid 0

Within 2000' of a Residential Building Unit within a Disproportionately Impacted Community 0

Within High Priority Habitat 1

Detected Leak on Operator's CDPHE/AQCC Reg 7 Delayed Repair List 0

Form Submit Date: 05/09/2024

Plugging Due Date For Wells: 05/09/2028

#	Inv	API	Well Name & Number	Date Ceased Production or Utilization	Within 2000' of a School Facility?	Within 2000' of a Child Care Center?	Within 2000' of a High Occupancy Building Unit?	Within 2000' of a Residential Building Unit within a Disproportionately Impacted Community?	Within High Priority Habitat?	Detected Leak on Operator's CDPHE/AQCC Reg 7 Delayed Repair List?
1		001-06878	UPRR-LINNEBUR 1	08/01/2020	No	No	No	No	No	No
2		001-07050	FLADER INDUSTRIES 1	11/01/2020	No	No	No	No	No	No
3		001-08925	LINNEBUR 2-R	06/01/2021	No	No	No	No	No	No
4		005-06688	AMOCO-UPRR-NOONEN-PRICE 1	05/01/2023	No	No	No	No	No	No
5		005-06731	LINNEBUR 1-6	12/21/2021	No	No	No	No	Yes	No

Date Run: 5/9/2024 Doc [#403775931]

Page 1 of 2

OPERATOR COMMENT AND SUBMITTAL

I hereby certify all statements made on this form are, to the best of my knowledge at the time of submittal, true, correct, and complete.

--

Print Name: <u>Jessica Donahue</u>	Email: <u>jdonahue@ardorenvironmental.com</u>
Title: <u>Compliance Specialist</u>	Date: <u>05/09/2024</u>

ATTACHMENT LIST**Att Doc Num****Name**

403776748	EDD-DESIGNATION
-----------	-----------------

Total Attach: 1 Files