

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2024

Submitted Date:

05/07/2024

Document Number:

697009510

FIELD INSPECTION FORMLoc ID 326934 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246086	WELL	SI	04/01/2023	OW	123-13883	STROH 35-1	SI

General Comment:

This is a routine inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator personnel on location at the time of this field inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead sign is not currently posted and requires replacement, see attached photos.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/14/2024

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		,	
Comment:	Location #326936					
Corrective Action:				Date:		

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Venting:</u>		
Yes/No	NO	
Comment:		
Corrective Action:		Date: <input type="text"/>
<u>Flaring:</u>		
Type		
Comment:		
Corrective Action:		Date: <input type="text"/>

Inspected Facilities									
Facility ID:	246086	Type:	WELL	API Number:	123-13883	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned									
Reminder:									
Comment:									
Corrective Action:									
Date:									
BradenHead									
Date of Last Brhd Test: 01/22/2024									
Annual Brhd Completed? Yes									
Last Brhd Test Results									
Initial Surf Csg Pressure: 0									
Fluid Type:									
End Surf Csg Pressure: 0									
Comment:									
Corrective Action:									
Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 5/7/2024 at approximately 15:00 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy Stroh 35-1 location #326934 in Weld County, Colorado.</p> <p>While there, I observed that the wellhead sign was not posted and required replacement. During this inspection the following possible compliance issues were observed: Rule 605.d. with a corrective action date of 6/14/2024.</p> <p>A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	05/07/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403782808	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539581
697009511	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539580