

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2024

Submitted Date:

05/07/2024

Document Number:

709100280

FIELD INSPECTION FORM

Loc ID 337805 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: ☐

Operator Information:

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Dolezal, Pat		pat.dolezal@ownresources.com	Inspections
Abdul Elnajdi		abdul.elnajdi@state.co.us	
Kilian Collins		kilian.collins@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288720	WELL	PR	04/01/2021	GW	125-10612	KNODEL 42-16	EI
444621	SPILL OR RELEASE	CL	02/16/2022		-	SPILL/RELEASE POINT	EI

General Comment:

On April 24, 2024, ECMC Environmental Unit Staff Krystal Heibel, Kilian Collins, and Abdul Alnajdi inspected the Knodel 42-16 location (Location ID: 337805).

Open Remediation #21960 at this Location.

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	Location observed to have no vegetation growing (potential salt kill) along the road.		
Corrective Action:	Operator shall remediate the historic release by delineating horizontal and vertical extent of impacted area using the Table 915-1 Protection of Groundwater Soil Screening Level Concentrations and remediate impacts to Table 915-1 standards. Documentation must include a figure showing spill area with sample locations plus laboratory results. This informations shall be submitted within the next Form 27 submittal.		Date: <u>07/07/2024</u>

Overall Good: ☐

Spills:				
Type	Area	Volume		
Lube Oil	WELLHEAD			
Comment:	Hydrocarbons observed at the wellhead and around the surrounding soil. See photo documentation.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: <u>07/07/2024</u>

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 288720	Type: WELL	API Number: 125-10612	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 444621	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403782437	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539214
709100281	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539207