

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2024

Submitted Date:

05/07/2024

Document Number:

709100284

FIELD INSPECTION FORM

Loc ID 337808 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: ☐

Operator Information:

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Abdul Elnajdi		abdul.elnajdi@state.co.us	
Kilian Collins		kilian.collins@state.co.us	
Dolezal, Pat		pat.dolezal@ownresources.co m	Inspections
Krystal Heibel		krystal.heibel@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288757	WELL	PR	08/01/2008	GW	125-10615	KNODEL 11-16	EI
484615	SPILL OR RELEASE	AC	06/20/2023		-	Knodel 11-16	EI

General Comment:

On April 24, 2024, ECMC Environmental Unit Staff Krystal Heibel, Kilian Collins, and Abdul Alnajdi inspected the Knodel 11-16 location (Location ID: 337808).

Open Remediation #34576 at this Location.

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type				
Comment:	Location observed to have no vegetation growing (potential salt kill) west of the location.			
Corrective Action:	Operator shall remediate the historic release by delineating horizontal and vertical extent of impacted area using the Table 915-1 Protection of Groundwater Soil Screening Level Concentrations and remediate impacts to Table 915-1 standards. Documentation must include a figure showing spill area with sample locations plus laboratory results. This informations shall be submitted within the next Form 27 submittal.			Date: 07/07/2024
Type	WEEDS			
Comment:	Tumbleweeds located within containment.			
Corrective Action:	Comply with Rule 606.			Date: 05/14/2024
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date: _____
Flaring:				
Type				
Comment:				
Corrective Action:				Date: _____

Inspected Facilities									
Facility ID:	288757	Type:	WELL	API Number:	125-10615	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	484615	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403782443	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539216
709100285	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539209