

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/24/2024

Submitted Date:

05/07/2024

Document Number:

709100286**FIELD INSPECTION FORM**Loc ID 337803 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kyle Waggoner		kyle.waggoner@state.co.us	
Kilian Collins		kilian.collins@state.co.us	
Abdul Elnajdi		Abdul.elnajdi@state.co.us	
Dolezal, Pat		pat.dolezal@ownresources.com	Inspections
Krystal Heibel		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288723	WELL	PR	08/01/2008	GW	125-10610	KNODEL 14-16	EI
482980	SPILL OR RELEASE	AC	09/23/2022		-	Knodel 14-16	EI

General Comment:

On April 24, 2024, ECMC Environmental Unit Staff Krystal Heibel, Kilian Collins, and Abdul Alnajdi inspected the Knodel 14-16 location (Location ID: 337803).

Open Remediation #34287 at this Location.

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment observed within fenced area.		
Corrective Action:	Comply with Rule 606.		Date: 08/07/2024
Type	OTHER		
Comment:	Location observed to have no vegetation growing (potential salt kill) northeast of the location.		
Corrective Action:	Operator shall remediate the historic release by delineating horizontal and vertical extent of impacted area using the Table 915-1 Protection of Groundwater Soil Screening Level Concentrations and remediate impacts to Table 915-1 standards. Documentation must include a figure showing spill area with sample locations plus laboratory results. This informations shall be submitted within the next Form 27 submittal.		Date: 06/07/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		
Lube Oil	WELLHEAD			
Comment:	Hydrocarbons observed at the wellhead and around the surrounding soil. See photo documentation.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date:	07/07/2024

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 288723	Type: WELL	API Number: 125-10610	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 482980	Type: SPILL OR	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403782444	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539217
709100287	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6539210