

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2024

Submitted Date:

05/16/2024

Document Number:

694100357

FIELD INSPECTION FORMLoc ID 332625 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections
,		cogccinspections@oxy.com	
,		ECMCInspections@Oxy.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 332625 West Farm 4-14. Please note that the Loc ID is for the associated wellhead while the inspection is for the tank battery. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment:

Statewide unnecessary equipment, weeds, waste, and trash requirements.

Trash/plastic material within separator secondary containment. Pile of possibly burnt wood material near the entrance of the site (West side).

Corrective Action:

Comply with Rule 606

Date: 05/30/2024Overall Good: ☐**Spills:**

Type

Area

Volume

Comment:

De minimus oil spot observed, likely from parked vehicle/truck.
Use for spills/releases of non E&P waste. Fueling areas, chemical storage, diesel tanks, smaller containers of refined oil products or chemical drums and totes.

Corrective Action:

Immediately clean up of spilled material. 10 days to implement improved procedures as long as no further spill or release of material

Date: 05/23/2024

In Containment: No

Comment:

De minimus oil spot observed.
Use for spills/releases of non E&P waste. Fueling areas, chemical storage, diesel tanks, smaller containers of refined oil products or chemical drums and totes.☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: Metal Secondary containment at the separator is bent at the western wall and is therefore STILL not sufficiently impervious to contain potentially spilled or released materials. If this issue is not addressed within the allotted 30-day time period, enforcement action may be warranted.					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.					Date: <u>06/13/2024</u>

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:

No spills or releases observed other than the de minimus oil spot observed on the site.

Corrective Action:

Date:

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :LatLong

Field Parameters:

Sample Location:Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694100373	photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6551064