

FORM 6 <small>Rev 11/20</small>	State of Colorado Energy & Carbon Management Commission <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>				<div style="border: 1px solid black; padding: 2px;">DE</div> <div style="border: 1px solid black; padding: 2px;">ET</div> <div style="border: 1px solid black; padding: 2px;">OE</div> <div style="border: 1px solid black; padding: 2px;">ES</div>																														
	WELL ABANDONMENT REPORT				<div>Document Number: 403715045</div> <div>Date Received: 03/11/2024</div>																														
<small>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</small>																																			
<table style="width:100%;"><tr><td style="width:50%;">ECMC Operator Number: 47120</td><td style="width:50%;">Contact Name: Candice Barber</td></tr><tr><td>Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP</td><td>Phone: (307) 2334513</td></tr><tr><td>Address: P O BOX 173779</td><td>Fax:</td></tr><tr><td>City: DENVER State: CO Zip: 80217-</td><td>Email: candice_barber@oxy.com</td></tr></table>						ECMC Operator Number: 47120	Contact Name: Candice Barber	Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Phone: (307) 2334513	Address: P O BOX 173779	Fax:	City: DENVER State: CO Zip: 80217-	Email: candice_barber@oxy.com																						
ECMC Operator Number: 47120	Contact Name: Candice Barber																																		
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Phone: (307) 2334513																																		
Address: P O BOX 173779	Fax:																																		
City: DENVER State: CO Zip: 80217-	Email: candice_barber@oxy.com																																		
<table style="width:100%;"><tr><td style="width:30%;">For "Intent" 24 hour notice required,</td><td style="width:35%;">Name: _____</td><td style="width:35%;">Tel: _____</td></tr><tr><td>ECMC contact:</td><td>Email: _____</td><td></td></tr></table>						For "Intent" 24 hour notice required,	Name: _____	Tel: _____	ECMC contact:	Email: _____																									
For "Intent" 24 hour notice required,	Name: _____	Tel: _____																																	
ECMC contact:	Email: _____																																		
Type of Well Abandonment Report: <input type="checkbox"/> Notice of Intent to Abandon <input checked="" type="checkbox"/> Subsequent Report of Abandonment																																			
<table style="width:100%;"><tr><td style="width:20%;">API Number</td><td colspan="5">05-123-21274-00</td></tr><tr><td>Well Name:</td><td colspan="2">ANDERSON</td><td colspan="3">Well Number: 3-34A</td></tr><tr><td>Location:</td><td>QtrQtr: NENW</td><td>Section: 34</td><td>Township: 3N</td><td>Range: 68W</td><td>Meridian: 6</td></tr><tr><td>County:</td><td colspan="2">WELD</td><td colspan="3">Federal, Indian or State Lease Number: _____</td></tr><tr><td>Field Name:</td><td colspan="2">WATTENBERG</td><td colspan="3">Field Number: 90750</td></tr></table>						API Number	05-123-21274-00					Well Name:	ANDERSON		Well Number: 3-34A			Location:	QtrQtr: NENW	Section: 34	Township: 3N	Range: 68W	Meridian: 6	County:	WELD		Federal, Indian or State Lease Number: _____			Field Name:	WATTENBERG		Field Number: 90750		
API Number	05-123-21274-00																																		
Well Name:	ANDERSON		Well Number: 3-34A																																
Location:	QtrQtr: NENW	Section: 34	Township: 3N	Range: 68W	Meridian: 6																														
County:	WELD		Federal, Indian or State Lease Number: _____																																
Field Name:	WATTENBERG		Field Number: 90750																																
<i>Only Complete the Following Background Information for Intent to Abandon</i>																																			
<table style="width:100%;"><tr><td style="width:30%;">Latitude: 40.188175</td><td style="width:30%;">Longitude: -104.991481</td><td colspan="3"></td></tr><tr><td>GPS Data: GPS Quality Value: 1.3</td><td>Type of GPS Quality Value: PDOP</td><td colspan="4">Date of Measurement: 03/04/2024</td></tr></table>						Latitude: 40.188175	Longitude: -104.991481				GPS Data: GPS Quality Value: 1.3	Type of GPS Quality Value: PDOP	Date of Measurement: 03/04/2024																						
Latitude: 40.188175	Longitude: -104.991481																																		
GPS Data: GPS Quality Value: 1.3	Type of GPS Quality Value: PDOP	Date of Measurement: 03/04/2024																																	
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																																			
<input type="checkbox"/> Other _____																																			
Casing to be pulled: <input type="checkbox"/> Yes <input type="checkbox"/> No Estimated Depth: _____																																			
Fish in Hole: <input type="checkbox"/> Yes <input type="checkbox"/> No If yes, explain details below																																			
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input type="checkbox"/> No If yes, explain details below																																			
Details: _____																																			
Current and Previously Abandoned Zones																																			
<table style="width:100%;"><tr><th>Formation</th><th>Perf. Top</th><th>Perf. Btm</th><th>Abandoned Date</th><th>Method of Isolation</th><th>Plug Depth</th></tr><tr><td>CODELL</td><td>7202</td><td>7222</td><td>12/01/2023</td><td>RETAINER/SQUEEZED</td><td>6920</td></tr><tr><td>NIOBRARA</td><td>6950</td><td>7081</td><td>12/01/2023</td><td>RETAINER/SQUEEZED</td><td>6920</td></tr><tr><td>J SAND</td><td>7642</td><td>7664</td><td>11/30/2023</td><td>B PLUG CEMENT TOP</td><td>7560</td></tr></table>						Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth	CODELL	7202	7222	12/01/2023	RETAINER/SQUEEZED	6920	NIOBRARA	6950	7081	12/01/2023	RETAINER/SQUEEZED	6920	J SAND	7642	7664	11/30/2023	B PLUG CEMENT TOP	7560						
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																														
CODELL	7202	7222	12/01/2023	RETAINER/SQUEEZED	6920																														
NIOBRARA	6950	7081	12/01/2023	RETAINER/SQUEEZED	6920																														
J SAND	7642	7664	11/30/2023	B PLUG CEMENT TOP	7560																														
Total: 3 zone(s)																																			
Casing History																																			

<u>COA Type</u>	<u>Description</u>
0 COA	

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
403715045	WELL ABANDONMENT REPORT (SUBSEQUENT)
403715077	OPERATIONS SUMMARY
403715081	OTHER
403715082	CEMENT JOB SUMMARY
403715083	OTHER
403715084	WELLBORE DIAGRAM
403715087	WIRELINE JOB SUMMARY
403799665	FORM 6 SUBSEQUENT SUBMITTED

Total Attach: 8 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	2 months PA. Reviewed attachments. Pass.	05/21/2024

Total: 1 comment(s)