

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403817101

Date Received:

06/07/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Lacey Granillo

5057870118

lgranillo@logosresourcesllc.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000683

Inspection Date: 04/12/2024

FIR Submit Date: 04/17/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 307022

Location Name: ESPINOSA-N32N6W Number: 16SWSE County: \_\_\_\_\_

Qtrqtr: SWSE Sec: 16 Twp: 32N Range: 6W Meridian: N

Latitude: 37.012790 Longitude: -107.503730

FACILITY - API Number: 05-067- -00 Facility ID: 307022

Facility Name: ESPINOSA-N32N6W Number: 16SWSE

Qtrqtr: SWSE Sec: 16 Twp: 32N Range: 6W Meridian: N

Latitude: 37.012790 Longitude: -107.503730

CORRECTIVE ACTIONS:

1 ☒ CA# 194302

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: 04/24/2024

Response: CA COMPLETED

Date of Completion: 06/07/2024

Operator  
Comment: Removed all debris and weeds.

ECMC Decision: Approved pending re-inspection

ed pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC

rules.



Comply with rule 1002 Install or repair required BMPs.

CA COMPLETED

Date of Completion: 06/07/2024

All BMP's have been repaired and location mulched.

Approved pending re-inspection

ed pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL	
1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
71	
72	
73	
74	
75	
76	
77	
78	
79	
80	
81	
82	
83	
84	
85	
86	
87	
88	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
100	

Removed all debris and weeds. All BMP's have been repaired and location mulched.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Lacey Granillo

Signed: \_\_\_\_\_

Regulatory Specialist

Date: 6/7/2024 9:11:19 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403817101	FIR RESOLUTION SUBMITTED
403817109	Espinosa 1A DOC 714000683 completed
403817110	Espinosa 1A DOC 714000683 completed
403817111	Espinosa 1A DOC 714000683 completed
403817112	Espinosa 1A DOC 714000683 completed
403817113	Espinosa 1A DOC 714000683 completed

Total Attach: 6 Files