

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2024

Submitted Date:

05/24/2024

Document Number:

710500286**FIELD INSPECTION FORM**Loc ID 312120 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 210 PARK AVENUE STE 2240City: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Costa, Ryan		ryan.costa@state.co.us	
Clark, Erin	405-319-3250	erin.k.clark@exxonmobil.com	Lead regulatory coordinator

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288598	WELL	PA	09/07/2022	OBW	071-09126	APACHE CANYON 6-9V	EI
292612	PIT	AC			-	APACHE CANYON 06-09V	EG

**General Comment:**

This is an Environmental Inspection for the Apache Canyon 06-09, Remediation location located in Las Animas County, Co. Remediation # 22832

Location				
<b>Lease Road:</b>				
Type				
comment:	Access road remains through well pad.			
Corrective ActionL			Date:	
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	Well Placard not posted.			
Corrective Action:	Install sign to comply with Rule 605.g.			Date: 06/25/2024
<b>Good Housekeeping:</b>				
Type	DEBRIS			
Comment:	There is debris and trash left on location. Remove Debris and cleanup trash Per Rule 606			
Corrective Action:			Date:	
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:			Date:	
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities									
Facility ID:	288598	Type:	WELL	API Number:	071-09126	Status:	PA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	292612	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental		
<b>Spill/Remediation:</b>		
Comment:	Remediation Project # 22832 is ongoing, Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area	
Corrective Action:		Date: _____
Emission Control Burner (ECB): _____		
Comment:		
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are signs of erosion on the cut slope of the location.

Stabilize erosion per Rule 1003 until the location is ready for final reclamation.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 292612Lat: 37.112027Long: -104.924293

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition:

Comment:

Remediation Project # 22832 for the pit is ongoing. There are fragments of pit liner left on the edges of the pit trench.

Remove fragmented pit liner and dispose in accordance with Rule 911.c.

Corrective Action

Date: \_\_\_\_\_

**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area	sanchezcc	05/24/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403810671	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571425">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571425</a>
710500287	Inspection 710500286 Location Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571399">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571399</a>