

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2024

Submitted Date:

05/24/2024

Document Number:

710500288

FIELD INSPECTION FORM

Loc ID: 333545 Inspector Name: Sanchez, Chris On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|------------------------|-----------------|
| Zeches, Giena | 719-220-4041 | gzeches@ogrisop.com | |
| BACA, DAVE | 719-859-4066 | dbaca@ogrisop.com | All Inspections |
| Costa, Ryan | | ryan.costa@state.co.us | |

General Comment:

This is an Environmental Inspection for the Apache Canyon 06-10, Remediation location located in Las Animas County, Co. Remediation # 22862

Location

| | | | |
|--------------------|---------------------------------------|-------|--|
| Lease Road: | | | |
| Type | | | |
| comment: | Access road remains through well pad. | | |
| Corrective ActionL | | Date: | |

Overall Good:

| | | | |
|----------------------------------|--|--|------------------|
| Emergency Contact Number: | | | |
| Comment: | No well placard identified on the location for the Apache Canyon 06-10 | | |
| Corrective Action: | Install sign to comply with Rule 605.a. | | Date: 06/25/2024 |

Overall Good:

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Environmental

Spill/Remediation:

Comment: Remediation Project # 22862 is ongoing, Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Operator shall maintain BMPs and minimize erosion in accordance with Rule 1003 until the site is ready for final reclamation](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|-----------|------------|
| Operator will continue quarterly reporting until the site investigation is complete and Full Table 915-1 standards are met within the remediation area | sanchezcc | 05/24/2024 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------------|---|
| 403810673 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571426 |
| 710500289 | Inspection 710500288 Location Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6571400 |