

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2024

Submitted Date:

06/11/2024

Document Number:

715500185

FIELD INSPECTION FORM

Loc ID 316157 Inspector Name: Burchett, Kirby On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10775
Name of Operator: KT RESOURCES LLC
Address: 3381 WESTBROOK LANE
City: HIGHLANDS State: CO Zip: 80129

Findings:

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Adams, Karen	(303) 886-8733	adams@kt-res.com	
Gale, Tony	(303) 886-8733	tony@kt-res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232253	WELL	SI	05/01/2020	GW	103-09924	WRD UNIT 20-31	SI

General Comment:

[ECMC Inspection Report Summary](#)

On Tuesday, 06/11/2024, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the WRD Unit 20-31 well, Location #316157, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and Black Bear area with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #702501455 on 6/14/23. All Corrective Actions have been resolved.

While there during normal operations the following compliance issue was observed:

1. Gas calibration overdue.
2. Mechanical Integrity Test overdue.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (800) 288-0560 or 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:	Gas meter calibration out of compliance.			
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.		Date:	07/12/2024
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 232253 Type: WELL API Number: 103-09924 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut In - April 2020
April 2024 Production Report
Well is overdue for Mechanical Integrity Test (MIT). MIT requires 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.

Date: 07/15/2023

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500186	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6583345