

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2024

Submitted Date:

06/07/2024

Document Number:

710500305

FIELD INSPECTION FORM

Loc ID 308865 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, ENR	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284122	WELL	PR	07/11/2006	CBM	071-08743	PANHEAD 32-8	EI

General Comment:

[This is an Environmental Inspection for the Panhead 32-8 well location located in Las Animas County, Co](#)

Location

Lease Road:

Type	Access		
comment:	Water bypassing culverts at entrance to location		
Corrective Action:	Install and maintain BMPs per Rule 1002.f	Date:	07/09/2024

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Placard located on meter house. WDID sticker is illegible Update sign to comply with Rule 605.g.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	OTHER		
Comment:	Trees in sediment trap on West Side of location. Remove trees and maintain BMPs per Rule 1002.f.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV PLASTIC		
Comment: Produced water tank near separator needs cap reinstalled to prevent wildlife access					
Corrective Action: Install Cap to prevent wildlife access per Rule 608.a.(13)					Date: 06/14/2024

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:					
Corrective Action:				Date:	

Venting:

Yes/No				
Comment:				
Corrective Action:			Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 284122 Type: WELL API Number: 071-08743 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403817824	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578594
710500306	Inspection 710500305 Location Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6578585