

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403823840

Date Received:

06/13/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mattorano, Michael</u>	<u>575-445-6704/505-652-0416</u>	<u>mmattorano@wapitienergy.com</u>
<u>Beardslee, Tom</u>		<u>tom.beardslee@state.co.us</u>
<u>Madison, Randy</u>	<u>575-445-6706/575-420-1120</u>	<u>rmadison@wapitienergy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601099

Inspection Date: 06/10/2024

FIR Submit Date: 06/11/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: WAPITI OPERATING LLC

Company Number: 10351

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

LOCATION - Location ID: 307697

Location Name: VPR C-635S66W Number: 5SENE County: LAS ANIMAS

Qtrqtr: SENE Sec: 5 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.028410 Longitude: -104.795020

FACILITY - API Number: 05-071- -00 Facility ID: 89235

Facility Name: VPR C Number: 4

Qtrqtr: SENE Sec: 5 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.028410 Longitude: -104.795020

CORRECTIVE ACTIONS:

1 ☒ CA# 195791

Corrective Action: Comply with Rule 903.d.(2)  
Immediately cease venting.  
Submit form 4 to report gas venting.

Date: 06/13/2024

Response: CA COMPLETED

Date of Completion: 06/10/2024

When notified that the drip was venting to atmosphere it was closed immediately. It was determined it had been knocked open by wildlife. The valve was closed and plug installed to prevent this from happening in the future.

Operator Comment: Due to the fact this is a low pressure line and only 1 well on that lateral I estimate the volume to be 24 mcf. The volume lose did not show up on any SCADA readings. See attached Gas Analysis

ECMC Decision: Approved

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Thanks for the notification that this drip was venting.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy L. Madison

Signed: \_\_\_\_\_

Title: HSE & Reg. Specialist, Sr

Date: 6/13/2024 10:14:42 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403823840	FIR RESOLUTION SUBMITTED
403823909	Gas Analysis

Total Attach: 2 Files