

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403788770

Date Received:  
06/12/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

| Contact Name | Phone | Email                                     |
|--------------|-------|---|
| <u>TEP</u>   |       | <u>COGCCInspectionReports@terraep.com</u> |

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708301666  
Inspection Date: 02/12/2024 FIR Submit Date: 02/13/2024 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 335435

Location Name: WILLIAMS-66S96W Number: 33NENE County: \_\_\_\_\_  
Qtrqtr: NENE Sec: 33 Twp: 6S Range: 96W Meridian: 6  
Latitude: 39.484771 Longitude: -108.104641

### FACILITY - API Number: 05-045- -00 Facility ID: 335435

Facility Name: WILLIAMS-66S96W Number: 33NENE  
Qtrqtr: NENE Sec: 33 Twp: 6S Range: 96W Meridian: 6  
Latitude: 39.484771 Longitude: -108.104641

### CORRECTIVE ACTIONS:

1 ☒ CA# 191991

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 02/28/2024

Response: CA COMPLETED Date of Completion: 03/26/2024

Operator Comment: Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: 

Location and access road have been bladed/graded to remove rutting. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 6/12/2024 8:33:22 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

|           |                          |
|-----------|--------------------------|
| 403788770 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files