

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403794181

Date Received:  
06/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
.TEP COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708901960  
Inspection Date: 10/10/2023 FIR Submit Date: 10/14/2023 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 311612

Location Name: LAST DANCE-67S92W Number: 2NWSW County:  
Qtrqtr: NWS Sec: 2 Twp: 7S Range: 92W Meridian: 6  
W  
Latitude: 39.474291 Longitude: -107.639032

FACILITY - API Number: 05-045-00 Facility ID: 311612

Facility Name: LAST DANCE-67S92W Number: 2NWSW  
Qtrqtr: NWS Sec: 2 Twp: 7S Range: 92W Meridian: 6  
W  
Latitude: 39.474291 Longitude: -107.639032

CORRECTIVE ACTIONS:

1 CA# 185121

Corrective Action: The storage of equipment not necessary for use on location is prohibited. Date: 11/13/2023

Response: CA COMPLETED Date of Completion: 10/23/2023

Operator Comment: ECD has been connected and is currently being used for the facility. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

2 CA# 185122

Corrective Action: All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.

Date: 10/28/2023

Response: CA COMPLETED

Date of Completion: 05/02/2024

Operator Comment: Deadman has been marked. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

3 CA# 185123

Corrective Action: Comply with Rule 605, fix labels & add required information

Date: 11/13/2023

Response: CA COMPLETED

Date of Completion: 05/02/2024

Operator Comment: Methanol tank labels have been replaced. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

4 CA# 185124

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 10/29/2023

Response: CA COMPLETED

Date of Completion: 05/02/2024

Operator Comment: Rills have been repaired and areas exhibiting erosion have been stabilized. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA #185121: ECD has been connected and is currently being used for the facility. Corrective Action complete.  
CA #185122: Deadman has been marked. Corrective Action complete.  
CA #185123: Methanol tank labels have been replaced. Corrective Action complete.  
CA #185124: Rills have been repaired and areas exhibiting erosion have been stabilized. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 6/18/2024 5:34:27 AM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>

Total Attach: 0 Files