

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/17/2024

Submitted Date:

06/17/2024

Document Number:

715500267

FIELD INSPECTION FORM

Loc ID: 315347
Inspector Name: Burchett, Kirby
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

- 15 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus	(970) 285-2600	COGCC.inspections@caerusoilandgas.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230672	WELL	PR	03/30/2020	GW	103-08340	PICEANCE CREEK UNIT F23-18G	PR

General Comment:

[ECMC Inspection Report Summary](#)

On Monday, 06/17/2024, Inspector Kirby Burchett, conducted a routine field inspection at Caerus Piceance LLC on the Piceance Creek Unit F23-18G well, Location #315347, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Location is shared with 23-18 PWDD water transfer facility.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

1. No sign at tank battery.
 2. Relief riser missing protective cap.
 3. Production tank labels missing required information.
 4. March 2024 Production Report. April production report overdue.
- Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank missing required information. Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.		
Corrective Action:	All Tanks and Containers will be labeled pursuant to Rule 605. h. (1). All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information: Name of Operator; Operator's emergency contact telephone number; Tank capacity; Tank contents; and NFPA label or equivalent globally harmonized label.	Date:	06/28/2024
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No sign at tank battery.		
Corrective Action:	The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s); and Location, including the quarter/quarter section, of the Tank battery.	Date:	07/18/2024
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Corral panels. Concrete barricades.		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Corral panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Concrete barricades.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead tree		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Relief riser missing protective cap		
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.	Date:	07/03/2024
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	210
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:	Unlined			
Corrective Action:				Date:

Venting:	
-----------------	--

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 230672 Type: WELL API Number: 103-08340 Status: PR Insp. Status: PR

Producing Well

Comment: [March 2024 Production Report](#)
[April production report overdue](#)

Corrective Action: **Operators will report all existing oil and gas Wells that are not Plugged and Abandoned on the Form 7, Operator's Monthly Report of Operations within 45 days after the end of each month.**

Date: 07/18/2024

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						

Comment: [Operator is responsible for maintaining Best Management Practices \(BMPs\) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403827685	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6590305
715500268	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6590303