

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403837906

Date Received:
06/26/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

+

rbucogccinspectionreports@chevron.onmicrosoft.com

abbeynewby@chevron.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 709400861

Inspection Date: 03/04/2024

FIR Submit Date: 03/14/2024

FIR Status: _____

Inspected Operator Information:

Company Name: PETRO-CANADA RESOURCES (USA) INC

Company Number: 72085

Address: 5455 BRIGHTON BLVD

City: COMMERCE CITY State: CO Zip: 80022

LOCATION - Location ID: 376781

Location Name: DOWNING B-63S59W Number: 24NENW County: _____

Qtrqtr: NENW Sec: 24 Twp: 3S Range: 59W Meridian: 6

Latitude: 39.780966 Longitude: -103.936970

FACILITY - API Number: 05-001- -00 Facility ID: 376781

Facility Name: DOWNING B-63S59W Number: 24NENW

Qtrqtr: NENW Sec: 24 Twp: 3S Range: 59W Meridian: 6

Latitude: 39.780966 Longitude: -103.936970

CORRECTIVE ACTIONS:

1 CA# 193137

Corrective Action: Comply with Rule 606 weeds

Date: 03/22/2024

Response: CA COMPLETED

Date of Completion: 06/20/2024

Operator Comment: Mowed location and removed fence. We plan on managing weeds and inner seeding the site later in the fall and added the location to maintenance and monitoring program.

ECMC Decision: _____

Operator	Mowed location and removed fence. We plan on inner seeding the site later in the fall
Comment:	and added the location to maintenance and monitoring program.

ECMC Decision:

Operator Comment:	Recontouring would cause more damage to established vegetation and landowner did not allow this to work to be done.
-------------------	---

ECMC Decision:

--

Operator Comment:	Filled in and bladed ruts in shared operator access road.
-------------------	---

ECMC Decision:

Comment:	We plan on managing weeds and inner seeding the site later in the fall. The site has been added to the maintenance and monitoring program.
----------	--

Signed:

Date: 6/26/2024 9:38:48 PM

Page 2 of 3

<u>Document Number</u>	<u>Description</u>
403837907	photos

Total Attach: 1 Files