

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403780781

Date Received:  
05/17/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Luke Kelly	970-939-6353	lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201161  
Inspection Date: 04/17/2024 FIR Submit Date: 04/18/2024 FIR Status:

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 306270

Location Name: STATE PRONGHORN-65N61W Number: 16NWNW County:  
Qtrqtr: NWN Sec: 16 Twp: 5N Range: 61W Meridian: 6  
Latitude: 40.406420 Longitude: -104.220690

FACILITY - API Number: 05-123- -00 Facility ID: 306270

Facility Name: STATE PRONGHORN-65N61W Number: 16NWNW  
Qtrqtr: NWN Sec: 16 Twp: 5N Range: 61W Meridian: 6  
Latitude: 40.406420 Longitude: -104.220690

CORRECTIVE ACTIONS:

1 CA# 194401

Corrective Action: Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 05/18/2024

Response: CA COMPLETED

Date of Completion: 05/01/2024

Operator  
Comment:

Operator has reported that the location has been appropriately mowed to address weeds and undesirable vegetation. Operator has also noted that the location was stripped or remaining road-base, recontoured, re-seeded, and straw crimped to provide stabilization and promote growth. Location currently complies with Rule 1004.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 5/17/2024 12:26:45 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403780781	FIR RESOLUTION SUBMITTED
403795285	Inspection Resolution Report

Total Attach: 2 Files