

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403842393

Date Received:
07/01/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Ross, Rikki	970-896-5665	rikki.ross@fulcrumeo.com
Penner, annalee		annalee@fulcrumef.com
. Fulcrum		inspections@fulcrumeo.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 707800942
Inspection Date: 05/01/2024 FIR Submit Date: 05/10/2024 FIR Status:

Inspected Operator Information:

Company Name: FULCRUM ENERGY OPERATING LLC Company Number: 10805
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

LOCATION - Location ID: 421227

Location Name: Coalmont Number: 3-13H County:
Qtrqtr: SWS Sec: 13 Twp: 7N Range: 81W Meridian: 6
W
Latitude: 40.571353 Longitude: -106.441983

FACILITY - API Number: 05-057-00 Facility ID: 421227

Facility Name: Coalmont Number: 3-13H
Qtrqtr: SWS Sec: 13 Twp: 7N Range: 81W Meridian: 6
W
Latitude: 40.571353 Longitude: -106.441983

CORRECTIVE ACTIONS:

1 CA# 195089

Corrective Action: Remove stored equipment or put into service. Date: 06/28/2024

Response: CA COMPLETED Date of Completion: 05/17/2024

Stored equipment has been removed from location.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 195090

Corrective Action: Evacuate fluids in containments to provide adequate space in case of a spill

Date: 05/27/2024

Response: CA COMPLETED

Date of Completion: 06/17/2024

Operator
Comment: Containment has been evacuated.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Fulcrum also completed all corrective actions noted in the inspection photos - API added to battery signage, debris cleaned up, and open holes have been closed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed:

Title: EHS Field Advisor

Date: 7/1/2024 5:29:25 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files