

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403845350

Date Received:  
07/03/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 760 HORIZON DRIVE STE 400  
City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Burchett, Kirby		kirby.burchett@state.co.us
. Inspections	(970) 675-7928	inspections@utahgascorp.com
Roberts, James		j75rober@blm.gov

ECMC INSPECTION SUMMARY:

FIR Document Number: 696205916  
Inspection Date: 06/19/2024 FIR Submit Date: 06/21/2024 FIR Status:

Inspected Operator Information:

Company Name: UTAH GAS OP LTD DBA UTAH GAS CORP Company Number: 10539  
Address: 760 HORIZON DRIVE STE 400  
City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 315466

Location Name: THUNDER COM B-64S102W Number: 29NWSE County:  
Qtrqtr: NWSE Sec: 29 Twp: 4S Range: 102W Meridian: 6  
Latitude: 39.669931 Longitude: -108.863291

FACILITY - API Number: 05-103-00 Facility ID: 315466

Facility Name: THUNDER COM B-64S102W Number: 29NWSE  
Qtrqtr: NWSE Sec: 29 Twp: 4S Range: 102W Meridian: 6  
Latitude: 39.669931 Longitude: -108.863291

CORRECTIVE ACTIONS:

1 CA# 196023

Corrective Action: Comply with Rule 1003.f and 606.c- Oil and Gas Locations will be kept free of all Undesirable Plant Species.

Date: 07/06/2024

Response: CA COMPLETED

Date of Completion: 07/02/2024

Operator Comment: Removed weeds from location.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 196024

Corrective Action: Comply with Rule 1002.f- Install or repair required stormwater and erosion control measures to manage runoff in a manner that minimizes erosion, degradation and sediment transport. Ensure BMPs are adequate for the site's conditions, installed per good engineering practices and maintained in a proper functioning condition.

Date: 07/06/2024

Response: CA COMPLETED

Date of Completion: 07/03/2024

Operator  
Comment:

Installed stormwater erosion control BMPs to manage runoff in a way that minimizes erosion.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The attached photos show compliance with ECMC's corrective action issued on 6/19/2024. Utah Gas Corp has removed weeds from the location, and installed stormwater erosion control BMP's to manage runoff in a way that minimizes erosion.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: April Mestas

Signed: \_\_\_\_\_

Title: Regulatory Manager

Date: 7/3/2024 2:58:41 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403845366	Compliance photos

Total Attach: 1 Files