

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2024

Submitted Date:

06/27/2024

Document Number:

699506000**FIELD INSPECTION FORM**Loc ID 319762 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments8 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		gfritzler@bresnan.net	
Leonard, Mike		mike.leonard@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201286	WELL	PR	05/01/2023	OW	001-06689	LINNEBUR 4	PR

General Comment:

There have been no changes to equipment on location since previous inspection.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Risers on location are not LOTO		
Corrective Action:	Comply with rule 1105	Date:	06/06/2024
Type	OTHER		
Comment:	wellhead sign incorrect.		
Corrective Action:	Comply with rule 605 d	Date:	06/06/2024
Type	OTHER		
Comment:	Locks on gate, unable to access location		
Corrective Action:	Comply with rule 204	Date:	06/06/2024
Type	OTHER		
Comment:	Guy line anchor is not marked properly		
Corrective Action:	Comply with rule 1003 a	Date:	06/06/2024
Type	OTHER		
Comment:	Contaminated soil near wellhead		
Corrective Action:	Comply with rule 905 e	Date:	06/06/2024
Type	OTHER		
Comment:	No production records since 12/1/23		
Corrective Action:	Comply with rule 429	Date:	06/06/2024
Type	OTHER		
Comment:	weeds unmanaged on location		
Corrective Action:	comply with rule 606	Date:	06/06/2024
Type	OTHER		
Comment:	no gas measurement equipment on location, provide how gas is measured on location, no midstream equipment		
Corrective Action:	Comply with rule 430	Date:	06/06/2024

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 201286 Type: WELL API Number: 001-06689 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/21/2023

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment

User

Date

ECMC Inspection Report Summary
 On 6/26/24 I, Inspector Justin Medina conducted an on-site inspection at:
 Well Name- Linnebur r
 Company Name- Fritzler resources INC
 API- 05-001-06689
 In Adams County Colorado.
 While there, I observed PR well
 This is a follow up inspection from document # 699505915 Corrective Actions are
 Delinquent
 During this inspection the following possible compliance issues were observed:
 OOSLOT LOTO. Rule 1105. 6/6/24
 wellhead sign. Rule 605 d. 6/6/24
 Weeds. Rule 606. 6/6/24
 Access. Rule 204. 6/6/24
 Deadmen anchors. Rule 1003. A. 6/27/24
 Production records. Rule 429. 6/6/24
 Contaminated soil. Rule 905 e. 6/6/24
 No gas measurement. Rule 430. 6/6/24
 A follow up on this site inspection needs to be conducted to ensure the compliance issues
 have been corrected to comply with ECMC rules.
 This is a summary of inspection report.

medinaj

06/27/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403839922	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6605572
699506001	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6605544