

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403819975

Date Received:

07/10/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 6 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201214

Inspection Date: 04/26/2024

FIR Submit Date: 05/10/2024

FIR Status: _____

Inspected Operator Information:

Company Name: EXTRACTION OIL & GAS INC

Company Number: 10459

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 440761

Location Name: Arellano Number: 10-L Pad County: _____

Qtrqtr: NESE Sec: 10 Twp: 5N Range: 65W Meridian: 6

Latitude: 40.410889 Longitude: -104.641133

FACILITY - API Number: 05-123-00 Facility ID: 440761

Facility Name: Arellano Number: 10-L Pad

Qtrqtr: NESE Sec: 10 Twp: 5N Range: 65W Meridian: 6

Latitude: 40.410889 Longitude: -104.641133

CORRECTIVE ACTIONS:

5 ☒ CA# 195085

Corrective Action: Comply with Rule 1003. Perform reclamation in accordance with Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date: 05/31/2024

Response: CA COMPLETED

Date of Completion: 05/31/2024

Operator Comment: Operator has reported that the location has been seeded, and straw crimped to provide stabilization and promote more uniform future growth. Operator also noted that the location was sprayed prior to interseeding actions to address weeds/additional undesirable vegetation. Location currently complies with Rule 1003.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: _____

Title: Sr Regulatory Analyst

Date: 7/10/2024 6:47:34 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403819975	FIR RESOLUTION SUBMITTED
403819982	Inspection Report Resolution

Total Attach: 2 Files