

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403860541

Date Received:

07/22/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708901678

Inspection Date: 09/14/2023

FIR Submit Date: 09/17/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 323824

Location Name: MOBIL-66S95W Number: 33NWSE County: _____

Qtrqtr: NWSE Sec: 33 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.478069 Longitude: -107.998753

FACILITY - API Number: 05-045- -00 Facility ID: 323824

Facility Name: MOBIL-66S95W Number: 33NWSE

Qtrqtr: NWSE Sec: 33 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.478069 Longitude: -107.998753

CORRECTIVE ACTIONS:

1 ☒ CA# 181366

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved.

Date: 10/02/2023

Response: CA COMPLETED

Date of Completion: 09/26/2023

Operator Comment: Location and access road have been bladed/graded to remove rills and increase stabilization. Off location rills have been repaired. Corrective Action complete.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Location and access road have been bladed/graded to remove rills and increase stabilization. Off location rills have been repaired. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 7/22/2024 7:50:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

403860541	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files