

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2024

Submitted Date:

07/29/2024

Document Number:

697602402**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Ahmadian, Alexander 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments7 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, John		jpetereson@kpk.com	<a href="#">KPK environmental</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Anderson, Laurel		laurel.anderson@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
Brown, Kari		kari.oakman@state.co.us	

**General Comment:**

This is an environmental inspection to determine progress on Spill ID 474780 / Remediation Project No 15825. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road was blocked off by orange fencing. The orange fencing has been completely torn down and is now considered trash onsite.		
Corrective Action:	Oil and Gas Facilities will be adequately fenced to restrict access by unauthorized persons, if determined necessary by the Director.	Date:	08/05/2024

Overall Good: ☐

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash in abundance throughout the location		
Corrective Action:	Comply with Housekeeping Rule 606.	Date:	08/05/2024
Type	WEEDS		
Comment:	Weeds overgrown at the location		
Corrective Action:	Comply with Housekeeping Rule 606.	Date:	08/05/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Fencing is down around the excavation.		
Corrective Action:	The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.	Date:	08/05/2024

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: The last Form 27 Supplemental was submitted on 11/03/2022. Operator has not submitted a form within the approved quarterly reporting schedule and Rule 913.e.(3); the next quarterly report was due 02/01/2023.

Corrective Action: Operator shall immediately submit a Form 27 for Spill ID 474780 that includes a specific workplan and timeline to address the remaining impacts.

Date: 02/01/2023

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_

Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: Spill remains open. Excavation is still open and no additional remedial work has been done on site. No analytical has been submitted for this project to date.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Vehicle tracking is installed improperly or not adequately maintained to prevent track of material offsite. The gravel has been filled in with dirt/mud and does not prevent tracking.				
Corrective Action:		Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. Additionally, if material is tracked onto county or public roads, contact the appropriate authority.				Date: 07/30/2024
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
The site is in poor condition. The site has been neglected and no remediation has been completed at the site since the last inspection.	ahmadiaa	07/29/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602403	Photolog	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642775">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642775</a>