

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2024

Submitted Date:

07/30/2024

Document Number:

715500484

**FIELD INSPECTION FORM**Loc ID 316275 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

12 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Enforcement, ECMC		dnr_cogccenforcement@state.co.us	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260267	WELL	SI	03/01/2024	GW	103-10138	WRD FEDERAL 19-33	SI

**General Comment:****ECMC Inspection Report Summary**

On Tuesday, 07/30/2024, Inspector Kirby Burchett, conducted a follow up field inspection at KT Resources LLC on the WRD Federal 19-33 well, Location #316275, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and Black Bear area with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #7702502192 on 8/29/23. The following Corrective Actions are unresolved and original due dates remain:

1. Weeds not maintained.
2. Chemical tank label faded and illegible.
3. Gas meter calibration out of compliance.

Refer to Inspection Photos for observed compliance issues.

While there during normal operations the following compliance issue was observed:

1. Stained soil.

Refer to Inspection Photo for observed compliance issue.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Faded and illegible labels on chemical tank		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	09/09/2023
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (800) 288-0560 or 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	No weed maintenance in 2023 or 2024.		
Corrective Action:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.	Date:	09/06/2023

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
PW/CO	Tank	<= 1 bbl	
Comment:	Staining at oil loadout and below produced water valve.		
Corrective Action:	Remove and properly dispose of impacted soil.		Date: 08/15/2024

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Chemical tank in containment	
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Gas meter calibration out of compliance.	
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.	Date: 09/09/2023
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Unlined				
Corrective Action:	Date:				
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:	Date:				

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment: <a href="#">Unlined</a>					
Corrective Action:				Date:	
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:				Date:	



Inspected Facilities									
Facility ID:	260267	Type:	WELL	API Number:	103-10138	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Shut in - March 2024 June 2024 Production Report</div>									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
Ditches						
Check Dams						
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715500485	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6645686">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6645686</a>