

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403853644

Date Received:  
07/15/2024

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Harms, Jason</u>		<u>Jason@strachanexploration.com</u>
<u>BEAR STACY L</u>		<u>stacy@strachanexploration.com</u>
<u>Enforcement</u>		<u>dnr_ecmcentforcement@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601179  
Inspection Date: 06/26/2024 FIR Submit Date: 06/27/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC Company Number: 83130  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

LOCATION - Location ID: 321213

Location Name: BOURNE-622S48W Number: 30SENW County: BENT  
Qtrqtr: SENW Sec: 30 Twp: 22S Range: 48W Meridian: 6  
Latitude: 38.108569 Longitude: -102.844847

FACILITY - API Number: 05-011-00 Facility ID: 206286

Facility Name: BOURNE Number: 1  
Qtrqtr: SENW Sec: 30 Twp: 22S Range: 48W Meridian: 6  
Latitude: 38.108569 Longitude: -102.844847

CORRECTIVE ACTIONS:

1  CA# 196188

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o. Date: 06/27/2024

Response: CA COMPLETED Date of Completion: 07/24/2024

Operator Comment: Filed a form 27 to remove the tank which is NOT in use. Approved 7/12 and will be removed as quickly as we can get equipment. Samples will be obtained under the tank per F27 specs. We will not rebuild the berm

ECMC Decision: Approved pending re-inspection

ECMC Representative: A follow up inspection will be performed to ensure tank is removed. FIRR including pictures should be submitted once tank has been removed.

**2**  CA# 196189

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 06/28/2024

Operator Comment: Disconnected separator, Dug up stained earth into 6ea 5 gal buckets and stored in secondary containment. Replumbed flow line around the separator position subsurface. form 19 was submitted but will request it be pulled due to volume being under the threshold.

ECMC Decision: Approved

ECMC Representative: \_\_\_\_\_

**3**  CA# 196190

Corrective Action: Comply with Rule 606. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 06/28/2024

Operator Comment: Riser near wellhead has been capped

ECMC Decision: Approved

ECMC Representative: \_\_\_\_\_

**4**  CA# 196191

Corrective Action: Comply with 606. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 07/24/2024

Operator Comment: Weeds within the bounds of the normal usage area have been pulled. The area around the perimeter will be mowed this week when equipment is on location

ECMC Decision: Approved pending re-inspection

ECMC Representative: As of 8/7/24, weeds had not been controlled.

**5**  CA# 196192

Corrective Action: Install sign to comply with Rule 605.e. Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 07/24/2024

Operator Comment: New wellhead signs ordered 6/28, Expect delivery this week and will install ASA received

ECMC Decision: Approved pending re-inspection

ECMC Representative: As of 8/7/24, the sign had not been installed. FIRR including pictures should be submitted once new sign is installed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

Form 27 for removal of tank and Separator were approved 7/12/24. Will finish up this week. MEOH tank will also be removed from Location when equipment is available

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Shawn Reed

Signed: \_\_\_\_\_

Title: Petroleum Consultant

Date: 7/15/2024 6:12:06 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403853644	FIR RESOLUTION SUBMITTED
403853649	Photo Riser
403853650	Excavated replumbed flow line

Total Attach: 3 Files