

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403884521

Date Received:

08/09/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 600 TRAVIS STREET SUITE 5050
City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: _____
Phone: () Fax: ()
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Tyler Faldyn	832-748-1090	tfaldyn@americanhelium.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 696204016
Inspection Date: 08/25/2022 FIR Submit Date: 08/29/2022 FIR Status: _____

Inspected Operator Information:

Company Name: LOCIN OIL CORPORATION Company Number: 51130
Address: 600 TRAVIS ST STE 6161
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 322320

Location Name: GOVERNMENT-66S104W Number: 35SWSW County: _____
Qtrqtr: SWS Sec: 35 Twp: 6S Range: 104W Meridian: 6
Latitude: 39.491823 Longitude: -108.962832

FACILITY - API Number: 05-045-00 Facility ID: 322320

Facility Name: GOVERNMENT-66S104W Number: 35SWSW
Qtrqtr: SWS Sec: 35 Twp: 6S Range: 104W Meridian: 6
Latitude: 39.491823 Longitude: -108.962832

CORRECTIVE ACTIONS:

1 CA# 164169

Corrective Action: Remove and properly dispose fluids within containment. Date: 09/13/2022

Response: CA COMPLETED Date of Completion: 12/06/2022

Operator Comment: Locin responded to this corrective action on Document #696204453 on 12/06/2023. We are submitting this FIRR to close the record.

ECMC Decision: _____

ECMC
Representative:

2 CA# 164170

Corrective Action: Comply with 605.h and post/label on all tanks with a capacity of 10 Barrels or greater, with the following information: A. Name of Operator; B. Operator's emergency contact telephone number; C. Tank capacity; D. Tank contents; and E. NFPA label or equivalent globally harmonized label. Lettering on all new Tanks, and on any reapplied or modified labels, will be legible from a distance of 100 feet.

Date: 09/29/2022

Response: CA COMPLETED

Date of Completion: 12/06/2022

Operator Comment: Locin responded to this corrective action on Document #696204453 on 12/06/2023. We are submitting this FIRR to close the record.

ECMC Decision: _____

ECMC
Representative:

3 CA# 164171

Corrective Action: Comply with Rule 606.c and keep Location and access road free of Undesirable Plant Species.

Date: 09/05/2022

Response: CA COMPLETED

Date of Completion: 12/06/2022

Operator Comment: Locin responded to this corrective action on Document #696204453 on 12/06/2023. We are submitting this FIRR to close the record.

ECMC Decision: _____

ECMC
Representative:

4 CA# 164172

Corrective Action: Install sign to comply with Rule 605.e.

Date: 09/29/2022

Response: CA COMPLETED

Date of Completion: 12/06/2022

Operator Comment: Locin responded to this corrective action on Document #696204453 on 12/06/2023. We are submitting this FIRR to close the record.

ECMC Decision: _____

ECMC
Representative:

5 CA# 164173

Corrective Action: Comply with 1002.f.; Implement and maintain BMPs to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation on access road. Ensure controls are implemented in accordance with good engineering practices and maintained in proper functioning condition; regrading alone will not be sufficient to stabilize road and manage runoff.

Date: 09/13/2022

Response: CA COMPLETED

Date of Completion: 12/06/2022

Operator Comment: Locin responded to this corrective action on Document #696204453 on 12/06/2023. We are submitting this FIRR to close the record.

ECMC Decision: _____

--

--

Date: 8/9/2024 1:47:24 PM

Total Attach: 1 Files