

Operator: HPR

Location Name: Critter Creek 24-30H

Loc ID: 420523

Inspection: 697505252



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Operator has performed final reclamation activities for the location and much of the location has desirable plant establishment with patches of unmanaged weeds. However, Operator has left an approximate 100' section of access road in-place and has failed to remove gravel, recontour and reclaim the access road. Comply with Rule 1004. Remove gravel, recontour, cross-rip access road to depth of eighteen (18) inches, reclaim the access road, and perform weed management throughout the location. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

CA Resolution: Operator has reported that this location mowed and sprayed for undesirable vegetation. The old access was scraped to remove remaining road-base material. Topsoil was imported to fill low areas in the access area and cap the access area. Area was ripped, seeded and straw crimped to provide stabilization. Location complies with Rule 1004.