

State of Colorado
Energy & Carbon Management Commission



Document Number:
403901278

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
08/29/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10503
Name of Operator: RED HAWK PETROLEUM LLC
Address: 575 N DAIRY ASHFORD STE 201
City: HOUSTON State: TX Zip: 77079
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Erin Ekblad</u>		<u>eekblad@pedevco.com</u>
<u>Kelsi Welch</u>		<u>kelsi.welch@iptwell.com</u>
<u>Charles Hinojosa</u>		<u>chinojosa@pedevco.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 696306633
Inspection Date: 08/09/2024 FIR Submit Date: 08/09/2024 FIR Status:

Inspected Operator Information:

Company Name: RED HAWK PETROLEUM LLC Company Number: 10503
Address: 575 N DAIRY ASHFORD STE 201
City: HOUSTON State: TX Zip: 77079

LOCATION - Location ID: 438327

Location Name: Loomis Number: 2-1H County:
Qtrqtr: SESW Sec: 2 Twp: 7N Range: 60W Meridian: 6
Latitude: 40.597730 Longitude: -104.062960

FACILITY - API Number: 05-123-00 Facility ID: 438327

Facility Name: Loomis Number: 2-1H
Qtrqtr: SESW Sec: 2 Twp: 7N Range: 60W Meridian: 6
Latitude: 40.597730 Longitude: -104.062960

CORRECTIVE ACTIONS:

1 CA# 197621

Corrective Action: Without an approved Gas Capture Plan or Variance, the well is to be shut in and conserved.
Form 7 reporting needs to be corrected to include all produced gas volumes. If access to infrastructure (gas gathering) has been terminated an updated Form 10 is required. Date: 08/19/2024

Response: CA COMPLETED Date of Completion: 08/19/2024

The well has been shut in while operations and equipment are being evaluated and reviewed to ensure full

Operator Comment: compliance. All applicable forms and documentation will be provided and/or updated prior to returning the well to production.

ECMC Decision: _____

ECMC Representative:

2 CA# 197622

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

Date: 08/16/2024

Response: CA COMPLETED

Date of Completion: 08/16/2024

Operator Comment: Stained soil has been removed & properly disposed of in accordance with 905.e.

ECMC Decision: _____

ECMC Representative:

3 CA# 197623

Corrective Action: Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.

Date: 08/16/2024

Response: CA COMPLETED

Date of Completion: 08/16/2024

Operator Comment: Flowline noted is a component of active gas buyback line, and per Operator does not need to be abandoned after evaluation.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please process this FIRR in place of FIRR doc #403895516. A request to delete the forementioned FIRR has been sent to the inspector as of 8/27/2024.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kelsi Welch

Signed: _____

Title: Permitting & Compliance

Date: 8/29/2024 10:42:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files