

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2024

Submitted Date:

08/29/2024

Document Number:

711901243**FIELD INSPECTION FORM**Loc ID 317333 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10536Name of Operator: SMITH ENERGY LLCAddress: 1540 MAIN ST SUITE 218 #334City: WINDSOR State: CO Zip: 80550**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Chris		smithenergy@live.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238107	WELL	PR	07/08/1998	GW	121-10610	PRICE 4-7X	PR

**General Comment:**[ROUTINE FIR - READ COMMENTS](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	MAINTAIN LEASE ROADS		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type			
Comment:	REPLACE STICKER PER 600 SERIES RULES		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: REPLACE STICKER PER 600 SERIES RULES

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: NONE

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 0		
Comment:	NO CHANGE		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	238107	Type:	WELL	API Number:	121-10610	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	GW								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

ECMC Comments		
Comment	User	Date
<a href="#">ROUTINE FIR - READ COMMENTS</a>	schureky	08/29/2024