

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403908760

Date Received:
09/04/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Caerus

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708904476

Inspection Date: 08/28/2024

FIR Submit Date: 09/02/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 324349

Location Name: HMU-68S93W Number: 2NESE County: _____

Qtrqtr: NESE Sec: 2 Twp: 8S Range: 93W Meridian: 6

Latitude: 39.393556 Longitude: -107.733083

FACILITY - API Number: 05-045-00 Facility ID: 324349

Facility Name: HMU-68S93W Number: 2NESE

Qtrqtr: NESE Sec: 2 Twp: 8S Range: 93W Meridian: 6

Latitude: 39.393556 Longitude: -107.733083

CORRECTIVE ACTIONS:

1 CA# 198252

Corrective Action: The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.

Date: 09/22/2024

Response: CA COMPLETED

Date of Completion: 09/03/2024

Operator Comment: Repaired liner. See photos.

ECMC Decision: _____

Date: 09/09/2024

Date of Completion: 09/03/2024

Covered flowline heating insulation opening. See photos

ECMC Decision: _____

--

--

Signed: _____

Date: 9/4/2024 6:59:25 AM

<u>Document Number</u>	<u>Description</u>
403908762	Flowline insulation covered.
403908763	Liner repaired.

Page 2 of 2