

TEP Rocky Mountain LLC
RG Federal 4D-34D
Location ID: 420072



When replaced additional information will be required



Label needs replaced

TEP Rocky Mountain LLC
RG Federal 4D-34D
Location ID: 420072



Relief riser missing protective cap



Not in use

**TEP Rocky Mountain LLC
RG Federal 4D-34D
Location ID: 420072**




Unused equipment and debris



Open end gas line with handle attached creating a hazard

**TEP Rocky Mountain LLC
RG Federal 4D-34D
Location ID: 420072**



Open end gas line with handle attached creating a hazard



Location from West corner

**TEP Rocky Mountain LLC
RG Federal 4D-34D
Location ID: 420072**



Location from South corner



Location from North corner