

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403910403

Date Received:
09/05/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10560
Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME ENERGYCO
Address: PO BOX 2326
City: VICTORIA State: TX Zip: 77902

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Johnny Horton</u>	<u>405-443-9818</u>	<u>jhorton@xecusa.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601125
Inspection Date: 06/13/2024 FIR Submit Date: 06/14/2024 FIR Status: _____

Inspected Operator Information:

Company Name: WEST TEXAS OPERATING CO LLC DBA XTREME ENERGYCO Company Number: 10560
Address: PO BOX 2326
City: VICTORIA State: TX Zip: 77902

LOCATION - Location ID: 321051

Location Name: MCKINLEY-633S43W Number: 20E2E2 County: BACA
Qtrqtr: SENE Sec: 20 Twp: 33S Range: 43W Meridian: 6
Latitude: 37.156613 Longitude: -102.279001

FACILITY - API Number: 05-009- -00 Facility ID: 205894

Facility Name: MCKINLEY Number: 1-20-WD
Qtrqtr: SENE Sec: 20 Twp: 33S Range: 43W Meridian: 6
Latitude: 37.156613 Longitude: -102.279001

CORRECTIVE ACTIONS:

1 CA# 195895

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o. and 902.b.

Date: 07/15/2024

Response: CA COMPLETED

Date of Completion: 09/20/2024

Operator Comment: Location Clean and Berms

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

2 CA# 195896

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 06/21/2024

Response: CA COMPLETED

Date of Completion: 06/15/2024

Operator Comment: The Compressor is not our unit it is the pipeline company machine (Badgers) We have no control over this equipment we called them about it.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

3 CA# 195897

Corrective Action: Conduct road maintenance per Rule 1002.f.(2)C.

Date: 07/15/2024

Response: CA COMPLETED

Date of Completion: 09/20/2024

Operator Comment: Location clean and completed

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

4 CA# 195898

Corrective Action: Comply with Rule 606.

Date: 07/15/2024

Response: CA COMPLETED

Date of Completion: 09/20/2024

Operator Comment: All equipment that belong to us and this well has been moved and cleaned up. we called Badger about any equipment that is not for this well.

ECMC Decision: Approved pending re-inspection

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mike Hahn

Signed: _____

Title: V P. Oper

Date: 9/5/2024 8:59:18 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403910403	FIR RESOLUTION SUBMITTED
403910442	Pics
403910445	Road Pics
403910448	Pics Loc

Total Attach: 4 Files