

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403933865

Date Received:
09/25/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

ENR

Phone

719-846-7898

Email

cogcc.evergreen@enrllc.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 710500358

Inspection Date: 09/10/2024

FIR Submit Date: 09/11/2024

FIR Status: _____

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC

Company Number: 10705

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 309357

Location Name: GOBLIN-631S67W Number: 36NWSW County: _____

Qtrqtr: NWS Sec: 36 Twp: 31S Range: 67W Meridian: 6
W

Latitude: 37.300930 Longitude: -104.846330

FACILITY - API Number: 05-071- -00 Facility ID: 309357

Facility Name: GOBLIN-631S67W Number: 36NWSW

Qtrqtr: NWS Sec: 36 Twp: 31S Range: 67W Meridian: 6
W

Latitude: 37.300930 Longitude: -104.846330

CORRECTIVE ACTIONS:

1 CA# 198682

Corrective Action: Pit liner compromised, repair or replace liner in accordance with Rule 910

Date: 09/18/2024

Response: CA COMPLETED

Date of Completion: 09/25/2024

Operator
Comment:

Pit liner repaired per rule 910

ECMC Decision: _____

ECMC Representative:	
-------------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment:

--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Dyke Signed: _____

Title: Construction Technician Date: 9/25/2024 10:55:26 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403933874	Pit liner repair

Total Attach: 1 Files