

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2024

Submitted Date:

09/25/2024

Document Number:

713601465

FIELD INSPECTION FORM

Loc ID 314203 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	
Sanchez, Chris		chris.sanchez@state.co.us	
STACY L BEAR		stacy@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444661	GAS COMPRESSOR STATION	SI	12/21/2016		-	NEU Compressor	RI

General Comment:

This is a follow up of the previous inspections #713600839, #713601194.
The corrective actions of the previous inspection have not been completed.
See attached photos and additional details within this report.

Location

Overall Good:

Signs/Marker:			
Type			
Comment:	Tank battery sign and labels are missing and faded		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/17/2024

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
	Tank		
Comment:	Previous inspection on 3/15/2024 observed a leak at the tank that spilled E&P waste within the tank secondary containment. The spill has not been cleaned up since the previous inspection. A form 19 has been submitted to report the spill. CA still remains to clean up the impacted soils.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 04/19/2024

In Containment: No
 Comment:
 Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:	<input type="text"/>		
Corrective Action:		Date:	

ECMC Comments

Comment	User	Date
A form 4 was submitted requesting replacement of the tank. Tank specification will need to comply with rule 603.k.	CostaR	09/25/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601466	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6721367