



<div>FORM 6</div> <div>Rev 11/20</div>	<div>State of Colorado</div> <div>Energy &amp; Carbon Management Commission</div> <div>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</div>	<div></div>	<table><tr><td>DE</td><td>ET</td><td>OE</td><td>ES</td></tr></table>	DE	ET	OE	ES																		
	DE	ET	OE	ES																					
<div>WELL ABANDONMENT REPORT</div> <div><p>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</p></div>			<div>Replug By Other Operator</div> <div>Document Number: 403874687</div> <div>Date Received:</div>																						
<table><tr><td>ECMC Operator Number: 10819</td><td>Contact Name: Venessa Chase</td></tr><tr><td>Name of Operator: PRAIRIE OPERATING CO LLC</td><td>Phone: (303) 907-1714</td></tr><tr><td>Address: 50 S STEELE STREET SUITE 450</td><td>Fax:</td></tr><tr><td>City: DENVER State: CO Zip: 80209</td><td>Email: vc@prairieopco.com</td></tr><tr><td>For "Intent" 24 hour notice required, Name: Petrie, Erica Tel: (303) 726-3822</td><td></td></tr><tr><td>ECMC contact: Email: erica.petrie@state.co.us</td><td></td></tr></table>				ECMC Operator Number: 10819	Contact Name: Venessa Chase	Name of Operator: PRAIRIE OPERATING CO LLC	Phone: (303) 907-1714	Address: 50 S STEELE STREET SUITE 450	Fax:	City: DENVER State: CO Zip: 80209	Email: vc@prairieopco.com	For "Intent" 24 hour notice required, Name: Petrie, Erica Tel: (303) 726-3822		ECMC contact: Email: erica.petrie@state.co.us											
ECMC Operator Number: 10819	Contact Name: Venessa Chase																								
Name of Operator: PRAIRIE OPERATING CO LLC	Phone: (303) 907-1714																								
Address: 50 S STEELE STREET SUITE 450	Fax:																								
City: DENVER State: CO Zip: 80209	Email: vc@prairieopco.com																								
For "Intent" 24 hour notice required, Name: Petrie, Erica Tel: (303) 726-3822																									
ECMC contact: Email: erica.petrie@state.co.us																									
<div>Type of Well Abandonment Report: <input checked="" type="checkbox"/> Notice of Intent to Abandon <input type="checkbox"/> Subsequent Report of Abandonment</div>																									
<table><tr><td>API Number 05-123-10675-00</td><td>Well Number: 1-6</td></tr><tr><td>Well Name: DOME HILL</td><td></td></tr><tr><td>Location: QtrQtr: SESE Section: 6 Township: 7N Range: 60W Meridian: 6</td><td></td></tr><tr><td>County: WELD</td><td>Federal, Indian or State Lease Number:</td></tr><tr><td>Field Name: MORNINGSIDE</td><td>Field Number: 56000</td></tr></table>				API Number 05-123-10675-00	Well Number: 1-6	Well Name: DOME HILL		Location: QtrQtr: SESE Section: 6 Township: 7N Range: 60W Meridian: 6		County: WELD	Federal, Indian or State Lease Number:	Field Name: MORNINGSIDE	Field Number: 56000												
API Number 05-123-10675-00	Well Number: 1-6																								
Well Name: DOME HILL																									
Location: QtrQtr: SESE Section: 6 Township: 7N Range: 60W Meridian: 6																									
County: WELD	Federal, Indian or State Lease Number:																								
Field Name: MORNINGSIDE	Field Number: 56000																								
<div>Only Complete the Following Background Information for Intent to Abandon</div> <table><tr><td>Latitude: 40.598715</td><td>Longitude: -104.128783</td></tr><tr><td>GPS Data: GPS Quality Value: 1.6</td><td>Type of GPS Quality Value: PDOP</td></tr><tr><td colspan="2">Date of Measurement: 08/14/2024</td></tr><tr><td colspan="2">Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems</td></tr><tr><td colspan="2"><input checked="" type="checkbox"/> Other Re-Enter and Re-Plug</td></tr><tr><td>Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</td><td>Estimated Depth:</td></tr><tr><td>Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</td><td>If yes, explain details below</td></tr><tr><td>Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</td><td>If yes, explain details below</td></tr><tr><td colspan="2">Details:</td></tr></table>				Latitude: 40.598715	Longitude: -104.128783	GPS Data: GPS Quality Value: 1.6	Type of GPS Quality Value: PDOP	Date of Measurement: 08/14/2024		Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems		<input checked="" type="checkbox"/> Other Re-Enter and Re-Plug		Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Estimated Depth:	Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If yes, explain details below	Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If yes, explain details below	Details:					
Latitude: 40.598715	Longitude: -104.128783																								
GPS Data: GPS Quality Value: 1.6	Type of GPS Quality Value: PDOP																								
Date of Measurement: 08/14/2024																									
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																									
<input checked="" type="checkbox"/> Other Re-Enter and Re-Plug																									
Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Estimated Depth:																								
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If yes, explain details below																								
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If yes, explain details below																								
Details:																									
<div>Current and Previously Abandoned Zones</div> <table><tr><th>Formation</th><th>Perf. Top</th><th>Perf. Btm</th><th>Abandoned Date</th><th>Method of Isolation</th><th>Plug Depth</th></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td></tr></table> <div>Total: 0 zone(s)</div>				Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																				
<div>Casing History</div> <table><tr><th>Casing Type</th><th>Size of Hole</th><th>Size of Casing</th><th>Grade</th><th>Wt/Ft</th><th>Csg/Liner Top</th><th>Setting Depth</th><th>Sacks Cmt</th><th>Cmt Btm</th><th>Cmt Top</th><th>Status</th></tr><tr><td>SURF</td><td>12+1/4</td><td>9+5/8</td><td>J55</td><td>36</td><td>0</td><td>353</td><td>300</td><td></td><td></td><td></td></tr></table>				Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status	SURF	12+1/4	9+5/8	J55	36	0	353	300			
Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status															
SURF	12+1/4	9+5/8	J55	36	0	353	300																		

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 145 sks cmt from 6500 ft. to 6000 ft. Plug Type: OPEN HOLE Plug Tagged: ☒  
Set 145 sks cmt from 2000 ft. to 1500 ft. Plug Type: OPEN HOLE Plug Tagged: ☒  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Type: \_\_\_\_\_ Plug Tagged: ☐  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
(Cast Iron Cement Retainer Depth)

Set 175 sacks half in. half out surface casing from 550 ft. to 0 ft. Plug Tagged: ☐  
Set \_\_\_\_\_ sacks at surface  
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No  
Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: \_\_\_\_\_  
Surface Plug Setting Date: \_\_\_\_\_ Cut and Cap Date: \_\_\_\_\_  
\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_  
Type of Cement and Additives Used: \_\_\_\_\_  
Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

See Plugging Procedure Attached.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Venessa Chase  
Title: Manager of Reg Affairs Date: \_\_\_\_\_ Email: vc@prairieopco.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

### CONDITIONS OF APPROVAL, IF ANY LIST

Expiration Date: \_\_\_\_\_

COA Type	Description
0 COA	

**ATTACHMENT LIST**

<b><u>Att Doc Num</u></b>	<b><u>Name</u></b>
403874693	WELLBORE DIAGRAM
403874694	PROPOSED PLUGGING PROCEDURE
403936119	LOCATION PHOTO
403936123	SURFACE OWNER CONSENT

Total Attach: 4 Files

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Permit	Sent back to draft since some attachments are missing	08/12/2024

Total: 1 comment(s)