

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2024

Submitted Date:

09/26/2024

Document Number:

709100408**FIELD INSPECTION FORM**Loc ID 406610 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 42950Name of Operator: INDUSTRIAL GAS SERVICES INCAddress: 5862 MCINTYRE COURTCity: GOLDEN State: CO Zip: 80403**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Oxford, Steven	(303) 422-3400	igsinc@att.net	
Kira Weber		kira.weber@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections
Kyle Waggoner		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
406610	LOCATION	CL			-	FRANKS-69N61W 33SESE	EI

General Comment:

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

Location			
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			
Corrective Action:		Date: _____	
Good Housekeeping:			
Type			
Comment:	Trash observed within the historic pit. See photo documentation; Comply with Rule 606		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:		corrective date	
Type:	#		
Comment:	Historic drill pit on location.		
Corrective Action:	Operator shall remediate the historic drill pit by submitting a proposed workplan (Form 27) to the ECMC. The proposed workplan shall include a Soil Sample Location Map that illustrates the location of soil borings to determine the presence or absence of impacts. Operator shall contact area EPS Krystal Heibel (krystal.heibel@state.co.us) for requirements and conditions of approval. Operator shall conduct a closure investigation in accordance with Rule 911.c. Pit Closure Guidance Document.		Date: 10/25/2024
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	406610	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100416	Pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6722704