

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2024

Submitted Date:

09/26/2024

Document Number:

710500380

FIELD INSPECTION FORM

Loc ID 321224 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	Strachan Exploration
L, Stacy		stacy@strachanexploration.com	Field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206345	WELL	SI	04/01/2024	GW	011-06092	STATE G 1	EI

General Comment:

This is an Environmental Inspection for the State G 1, API # 05-011-06092, located in Bent County, Colorado. There is an active remediation, Project # 24826, for the location.

Location

Lease Road:			
Type	Access		
comment:	Unable to access location due to Corn Field		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:			
Comment:	Unable to determine if placard is present on location		
Corrective Action:		Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 206345 Type: WELL API Number: 011-06092 Status: SI Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>There is an Active Remediation Project # 24826 for the well location.</p> <p>Form 27 Initial Document # 403147571 was submitted on 8/29/2022. Operator states the following in the Initial Action Summary; Strachan Exploration proposes to conduct closure operations of the State G#1 wellhead/location. Plugging operations will begin after the harvest in Q3/4 2022. Cut and cap operations will be performed a minimum of 5 days after the PTA is complete as per COGCC rules. we will perform appropriate site investigation and field screening pursuant to findings according to COGCC series 900 rules. PID surveys will be performed based on visual inspection. Should soil samples be needed based on visual inspection, they will be collected and analyzed in accordance per Rule 915, following the sampling guidelines in 915.e.(2). All waste generated during operations will be disposed of properly as directed in Rule 905 and 906. There are no facilities on this location.</p> <p>Operator shall implement Quarterly reporting for this remediation project and provide a standalone implementation schedule identifying when decommissioning activities will commence.</p> <p>Operator shall submit a Supplemental Form 27 for Remediation Project # 24826 by 10/7/2024</p>	sanchezcc	09/26/2024
Unable to access location due to Corn Field	sanchezcc	09/26/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500381	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6723204