

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/24/2024

Submitted Date:

09/26/2024

Document Number:

709100414**FIELD INSPECTION FORM**Loc ID 475344 Inspector Name: Heibel, Krystal On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	<a href="#">All Inspections</a>
Krystal Heibel		krystal.heibel@state.co.us	
Logan Hansen		logan.hansen@state.co.us	
Kyle Waggoner		kyle.waggoner@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475344	LOCATION	AC			-	WEST FORK UNIT-63S55W 19SWNW	EI

**General Comment:**

This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.

[Pleaser refer to Reclamation Inspection Report \(Doc# 713901008\) for additional details.](#)

**Location**Overall Good: ☐**Signs/Marker:**

Type			
Comment:	Placard and sign not posted on propane tank		
Corrective Action:		Date:	
Type			
Comment:	Sign not posted or information inaccurate at oil and gas location; Install sign to comply with Rule 605.a.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type			
Comment:	Trash (metal pipe, plastic) located at pit; Comply with Rule 606		
Corrective Action:		Date:	
Type			
Comment:	Vertical treater and horizontal tank not in use and stored on location; Comply with Rule 606		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil				
Comment:	Hydrocarbon stained soil observed under truck loadout & crude oil observed around the base of the vertical treater			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 10/26/2024

In Containment: No

Comment:

☒ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment:	Multiple valves open at tank battery and the vertical treater; Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		
Corrective Action:		Date:	
Type:	#		
Comment:	Wildlife protections devices not adequate for vertical treater; Install or repair wildlife protection equipment.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

Comment:							
Corrective Action:							Date:
<b><u>Paint</u></b>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<b><u>Berms</u></b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:	Holes located within berms; Repair or install berms or other secondary containment devices per Rule 603.o.						
Corrective Action:						Date:	
<b><u>Venting:</u></b>							
Yes/No							
Comment:							
Corrective Action:						Date:	
<b><u>Flaring:</u></b>							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities									
Facility ID:	475344	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume:

Comment: Operator shall investigate the historically impacted area southeast of pit# 107655 by submitting a proposed workplan (Form 27) to the ECMC.

Corrective Action: Operator shall contact area EPS Krystal Heibel (krystal.heibel@state.co.us) for requirements and conditions of approval. Operator shall include plans to vertically and horizontally delineate any potential impacts. Refer to the COAs on Doc# 403860299.

Date: 10/26/2024

Reportable:

GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:

Owner Name:

GPS :

Lat Long

Field Parameters:

Sample Location:

Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403936212	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6722729">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6722729</a>
709100415	Pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6722708">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6722708</a>

Date Run: 10/3/2024 Doc [#709100414]

Page 5 of 5