

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403909688

Date Received:

09/04/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

4 of 6 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Krystal Heibel

krystal.heibel@state.co.us

Kyle Waggoner

Kyle.waggoner@state.co.us

Bongers, Brent

361-935-5633

bbongers@impetroresources.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 709100341

Inspection Date: 06/26/2024

FIR Submit Date: 07/09/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: IMPETRO RESOURCES LLC

Company Number: 10690

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

#### LOCATION - Location ID: 317278

Location Name: CHANDLER-62N49W

Number: 15NWNE

County: \_\_\_\_\_

Qtrqtr: NWNE

Sec: 15

Twp: 2N

Range: 49W

Meridian: 6

Latitude: 40.145840

Longitude: -102.840590

#### FACILITY - API Number: 05-121-

-00

Facility ID: 317278

Facility Name: CHANDLER-62N49W

Number: 15NWNE

Qtrqtr: NWNE

Sec: 15

Twp: 2N

Range: 49W

Meridian: 6

Latitude: 40.145840

Longitude: -102.840590

### CORRECTIVE ACTIONS:

1 CA# 196594

Corrective Action: Repair berms around pits to prevent unauthorized E&P waste discharge.

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 07/12/2024

Operator  
Comment:

Pit berms have been repaired to prevent unauthorized E&P waste discharge.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 196595

Corrective Action: Prevent any unauthorized discharge and contain spills/releases and clean up per Rule 912.a.

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 07/12/2024

Operator  
Comment: Hydrocarbons have been properly cleaned and disposed of.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

3 CA# 196596

Corrective Action: Comply with Rule 606

Date: 07/16/2024

Response: CA COMPLETED

Date of Completion: 07/12/2024

Operator  
Comment: Per Rule 606, unused equipment has been removed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

6 CA# 196599

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/26/2024

Response: CA COMPLETED

Date of Completion: 07/12/2024

Operator  
Comment: Per Rule 608.e. all valves have been securely fasten to ensure good mechanical condition.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 9/4/2024 2:58:48 PM

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403909688	FIR RESOLUTION SUBMITTED
403909759	Photolog

Total Attach: 2 Files