

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403925065

Date Received:
09/17/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 55030

Name of Operator: MCCARTNEY ENGINEERING LLC

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ron McCartney</u>		<u>ron@mccartneyengineering.com</u>
<u>Amber Barnett</u>		<u>abarnett@ardorenvironmental.com</u>
<u>Krystal Heibel</u>		<u>krystal.heibel@state.co.us</u>
<u>Jack McCartney</u>		<u>jack@mccartneyengineering.com</u>
<u>Lisa McCartney</u>		<u>lisa@mccartneyengineering.com</u>
<u>Kyle Waggoner</u>		<u>kyle.waggoner@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 709100390

Inspection Date: 09/10/2024

FIR Submit Date: 09/17/2024

FIR Status: _____

Inspected Operator Information:

Company Name: MCCARTNEY ENGINEERING LLC

Company Number: 55030

Address: 4251 KIPLING ST STE 575

City: WHEAT RIDGE State: CO Zip: 80033

LOCATION - Location ID: 302966

Location Name: SEEDORF-62N48W Number: 21NWN County: _____

Qtrqr: NWNE Sec: 21 Twp: 2N Range: 48W Meridian: 6

Latitude: 40.130957 Longitude: -102.744856

FACILITY - API Number: 05-125- -00 Facility ID: 302966

Facility Name: SEEDORF-62N48W Number: 21NWN

Qtrqr: NWNE Sec: 21 Twp: 2N Range: 48W Meridian: 6

Latitude: 40.130957 Longitude: -102.744856

CORRECTIVE ACTIONS:

1 CA# 198823

Corrective Action: Outside of crop season, maintain lease road to comply with rule 204.

Date: 12/16/2024

Response: CA COMPLETED

Date of Completion: 09/17/2024

Operator Comment: The Seedorf #1 was P&A'd 10/19/2023. Shortly thereafter, the casing was cut off and capped, all lines and surface equipment removed. The flowline ROW and lease road were leveled and disked to accommodate ongoing farming operations. At the time of inspection, the field was plowed with organic fertilizer applied in preparation of wheat planting.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 198824

Corrective Action: In accordance with Rule 913.e.(3), Operator shall submit a Form 27 Supplemental quarterly (every 90 days) to remediate any spill/release and/or to close the remediation project.

Date: 10/16/2024

Response: CA COMPLETED

Date of Completion: 09/17/2024

Operator Comment: Form 27 Supplemental was submitted on 7/31/2024 detailing numerous soil samples analyzed to assist in determining the lateral and vertical extent of a saltwater spill. Additional soil samples have been taken for analysis to further define the extent of the spill. Results of continued remediation work will be timely reported on another Form 27.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: There is a small area of saltwater contamination with additional soil samples being analyzed to determine the lateral and vertical extent of contamination. The area was treated with organic material in conjunction with consultation with the landowner to augment fall wheat growth. Remediation plan will be timely submitted once the spill area is defined.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jack McCartney

Signed: _____

Title: Manager

Date: 9/17/2024 4:19:35 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403925065	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files