


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad
Location ID: 335412



**Location Overview: Location is within High Priority/Density
Habitat areas.**

Section/Township/Range: 18 6S94W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 132-18 Pad
Location ID: 335412



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.