

Interim Reclamation and Stormwater Inspection

September 10, 2024

Operator: FULCRUM ENERGY OPERATING # 10805

Location ID: 463987

Inspection Document #: 712300080

Jackson County, CO

Logan Maxwell
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Alcorn 0880 S10 Pad

Location ID: 463987



Photo 1. Photo taken from the entrance of Location, illustrating Operator's sign.



Photo 2. Photo taken the entrance of the Location, facing SE. Weeds observed growing along the perimeter. Photo illustrates failure of stormwater BMPs. Evidence of stormwater run-off outside of pad. Operator shall repair stormwater BMPs per Rule 1002.f.

Inspection Photos

Location Name: Alcorn 0880 S10 Pad

Location ID: 463987



Photo 3. Photo taken from the western pad surface, facing north. Photo illustrates erosion. Operator shall install/maintain stormwater BMPs per Rule 1002.f.(2)



Photo 4. Photo taken from the western pad surface, facing north. Photo illustrates failing BMPs. Operator shall install/maintain stormwater BMPs per Rule 1002.f.

Inspection Photos
Location Name: Alcorn 0880 S10 Pad
Location ID: 463987



Photo 5. Photo taken from the western pad edge, facing NE. Photo illustrates insufficient or missing perimeter BMPs. Operator shall comply with Rules 1002.f.

