

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403957059

Date Received:
10/15/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

CAERUS

ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302880

Inspection Date: 10/08/2024

FIR Submit Date: 10/08/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335670

Location Name: N.PARACHUTE-65S95W Number: 30SESW County: _____

Qtrqtr: SESW Sec: 30 Twp: 5S Range: 95W Meridian: 6

Latitude: 39.580910 Longitude: -108.098910

FACILITY - API Number: 05-045-00 Facility ID: 335670

Facility Name: N.PARACHUTE-65S95W Number: 30SESW

Qtrqtr: SESW Sec: 30 Twp: 5S Range: 95W Meridian: 6

Latitude: 39.580910 Longitude: -108.098910

CORRECTIVE ACTIONS:

1 CA# 199430

Corrective Action: Repair wildlife protective equipment.

Date: 10/13/2024

Response: CA COMPLETED

Date of Completion: 10/13/2024

Operator Comment: Repaired tank screen to prevent wildlife entrance.

ECMC Decision: _____

| | | | |
|--|----------------------|--|--|
| | ECMC Representative: | | |
|--|----------------------|--|--|

2

CA# 199431

Corrective Action:

Secure equipment to comply with Rule 608.e.

Date: 10/13/2024

Response: CA COMPLETED

Date of Completion: 10/13/2024

Operator Comment:

Installed bull plug on meter manifold to comply with rule 608.e.

ECMC Decision: _____

ECMC Representative:

3

CA# 199432

Corrective Action:

1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/23/2024

Response: CA COMPLETED

Date of Completion: 10/14/2024

Operator Comment:

Stormwater crew addressed cut slope that sloughed off into tank containment to comply with 1002.f.(2) BMP.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed: _____

Title: Compliance

Date: 10/15/2024 8:56:24 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|-----------------------------|
| 403957059 | FIR RESOLUTION SUBMITTED |
| 403957065 | Bullplug on meter manifold |
| 403957068 | Tank Screen |
| 403957074 | Stormwater tank containment |

Total Attach: 4 Files