

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403958628

Date Received:
10/15/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
2 of 2 CAs from the FIR responded to on this Form
2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10243
Name of Operator: GMT EXPLORATION COMPANY LLC
Address: 4949 S NIAGARA ST SUITE 250
City: DENVER State: CO Zip: 80237
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Maxwell Blair	303-586-9291	mblair@gmtexploration.com
BJ Cox	307-354-8895	bjcox@gmtexploration.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 697505397
Inspection Date: 07/17/2024 FIR Submit Date: 07/31/2024 FIR Status:

Inspected Operator Information:

Company Name: GMT EXPLORATION COMPANY LLC Company Number: 10243
Address: 4949 S NIAGARA ST SUITE 250
City: DENVER State: CO Zip: 80237

LOCATION - Location ID: 479197

Location Name: Marble-Redstone Number: Pad County:
Qtrqtr: NESW Sec: 24 Twp: 6S Range: 65W Meridian: 6
Latitude: 39.510864 Longitude: -104.617644

FACILITY - API Number: 05-039- -00 Facility ID: 479197

Facility Name: Marble-Redstone Number: Pad
Qtrqtr: NESW Sec: 24 Twp: 6S Range: 65W Meridian: 6
Latitude: 39.510864 Longitude: -104.617644

CORRECTIVE ACTIONS:

1 CA# 197206

Corrective Action: Best management practices to prevent weed establishment shall be implemented per Rule 1002.c. Control, manage, and prevent weedy, annual vegetation on all topsoil stockpiles. If reseeded is an option for long-term protection and stabilization of topsoil, then the next favorable seeding opportunity shall be conducted. Date: 10/15/2024

Response: CA COMPLETED Date of Completion: 10/15/2024

Weed mitigation measures were completed by August 30, 2024. Seeding is planned using seed mixture approved by property owner.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 197207

Corrective Action:

Perform additional reclamation in the above described area. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Date: 10/15/2024

Response: CA COMPLETED

Date of Completion: 10/15/2024

Operator
Comment:

Weed mitigation has been implemented, reseeding of owner approved seed mixture will occur when weather is favorable. It has been too warm this fall.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

Planning completed by ECMC requested completion date, reseeding will follow when weather is appropriate.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christopher Shephard

Signed: _____

Title: Consultant

Date: 10/15/2024 5:17:32 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files