


Antler Energy LLC
Federal Mountain Fuel 2-12
Location ID: 312976



When sign is replaced additional information is required



Labels need to be replaced when damaged, faded or illegible



**Antler Energy LLC
Federal Mountain Fuel 2-12
Location ID: 312976**



Open end tank valve



Debris

**Antler Energy LLC
Federal Mountain Fuel 2-12
Location ID: 312976**



Production pit



Production pit

**Antler Energy LLC
Federal Mountain Fuel 2-12
Location ID: 312976**



Unused equipment



Unused equipment

**Antler Energy LLC
Federal Mountain Fuel 2-12
Location ID: 312976**



Debris



Debris

**Antler Energy LLC
Federal Mountain Fuel 2-12
Location ID: 312976**



Location from Southeast corner



Location from Northeast corner

**Antler Energy LLC
Federal Mountain Fuel 2-12
Location ID: 312976**



Location from Northwest corner



Location from Southwest corner