

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2024

Submitted Date:

10/15/2024

Document Number:

693807831**FIELD INSPECTION FORM**Loc ID 334301 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10841Name of Operator: AMERICAN HELIUM OPERATING LLCAddress: 600 TRAVIS STREET SUITE 5050City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Hartman, Laura		lhartman@blm.gov	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257152	WELL	SI	06/01/2024	GW	113-06077	ANDYS MESA FEDERAL 14	PR
269548	WELL	SI	06/01/2024	GW	113-06131	ANDY'S MESA UNIT 41	PR

General Comment:

ECMC staff performed Optical Gas Imaging Survey inspection on 10/10/2024.
Issues were found requiring corrective action. See inspection text and photos for details.
[Any Corrective Actions from previous inspections that have not been addressed are still applicable.](#)

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/15/2024
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	435-631-2239	
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLS	PBV STEEL		38.057812,-108.644165
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		38.057812,-108.644165
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities									
Facility ID:	257152	Type:	WELL	API Number:	113-06077	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:	10/09/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	192	Fluid Type:	GAS					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	269548	Type:	WELL	API Number:	113-06131	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:	04/26/2023		Annual Brhd Completed?	No					
Last Brhd Test Results	Initial Surf Csg Pressure:	35	Fluid Type:	NONE					
	End Surf Csg Pressure:	0							
Comment:	No annual bradenhead test Form 17 on file.					11/15/2024			
Corrective Action:	Submit Form 17 as directed by Rule 419.c					Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: Routine

Current Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: 38.057800 Long: -108.644550

Wind: Calm Speed: (mph) Direction From: Weather: Clear Temperature: 89 (F)

Assisting Staff: Camera #: 2

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
-------------------	-------	-----------------	-------

Equipment Surveyed

Equipment
Separation Equipment
Water Tank(s)
Wellhead(s)

Comment: No FLIR detectable gas observed

Corrective Action:

Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403958266	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6747118
693807832	Inspection photos 10/10/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6747036